



[EN] LC16D/LS10 drive system firmware 2.18.0

Release notes

- Minor issue fixes and improvements.

All L-Acoustics devices of a system should always run the same firmware version.

Refer to the **LC16D** and **LS10** owner's manuals included in the downloaded package for detailed instructions.

Fixed issues

F1F-5119	LC16D with firmware version 2.17.2.3 in Normal network mode: The Ethernet port number 2 cannot be used to access the embedded Web interface.
----------	--

[FR] Firmware du système de pilotage LC16D/LS10 2.18.0

Notes de version

- Corrections de problèmes et améliorations mineures.

Tous les appareils L-Acoustics d'un système doivent toujours fonctionner avec la même version de firmware.

Référez-vous aux manuels du propriétaire **LC16D** et **LS10** inclus dans le pack téléchargé pour des instructions détaillées.

Problèmes résolus

F1F-5119	LC16D avec la version firmware 2.17.2.3 en mode de réseau Normal: Le port Ethernet numéro 2 ne permet pas d'accéder à l'interface Web embarquée.
----------	--